Kerala Circle

Doorsanchar Bhavan PMG junction Trivandrum 695 033 Telephone 0471-2302200, Fax 2305150 Email:cgm_kerala@bsnl.co.in



R. MANI ITS Chief General Manager

> D.O. No.OP/Gen/MIS/2016-17/17 14th July 2016

Dear Shri

To analyse the trend of churning of landline and broadband connections, you are requested to take immediate necessary actions on the following points.

- 1. Submission of feasibility status of pillars to Circle office.
 - The details required are the name, capacity, working connections and the status of faulty pairs/tags available.
- 2. Updating the faulty pair/tag details in the DCRMS package.
 - It is observe d that, in the DCRMS package, data regarding the status of faulty pairs are not updated which makes it difficult to declare a pillar feasible/non- feasible on first glance. So take necessary action to update the same at the earliest.
- 3. Preparation of route diagram up to the DPs.
 - Route diagrams may be prepared up to DP level for ready reference to the field units.

In this regard, your personal attention is required to ensure that the above points are executed positively at the earliest.

With best wishes,

Yours sincerely

Shri PGM/GM, BSNL Telecom District